V5-30-85

# SAN FRANCISCO HOUSING AUTHORITY

MODERNIZATION
NEEDS
INVENTORY

INSTITUTE OF GOVERNMENTAL STUDIES LIBRARY

MAY 29 1985

UNIVERSITY OF CALIFORNIA

MARCH 1985

REVISED MAY 1985



SAN FRANCISCO HOUSING AUTHORITY
MODERNIZATION NEEDS SURVEY
MARCH 1985

This document catalogs the identified physical problems present at each Authority public housing complex. Information regarding these items has been provided by residents and Authority management, maintenance, social and modernization staffs. As conditions at these projects are continously changing and as not everyone who is knowledgeable about these projects has yet to report their observations, this document does not pretend to list all of the existing problems. Revisions, therefore, will be made to this report as additional problems develop and as listed problems are corrected.

To put the scope of these problems into context, an estimated cost to address these conditions has been developed. It should be noted, however, that in many cases these cost estimates are initial projections. As a detailed analysis of each problem is made and appropriate solutions developed, these estimates will be refined.



	HEALTH			MANAGEAB IL ITY	ii
	AND SAFETY	DETERIORATION	LIVEABILITY	N D	
PROJECT	CODES GAS REPAIRS APT. SECURITY SITE SECURITY	BOILERS PLUMBING ELECTRICAL. ROOFS ELEVATORS APT. REPAIRS MAIL BOXES GARBAGE CHUTES WINDOWS EXTERIOR REPAIRS EXTERIOR PAINT SITE REPAIRS	APT. MODERNIZE HANDICAPPED PRIVATE YARDS LANDSCAPE PLAY AREAS COMMUNITY SPACE CHILD CARE	PUBLIC AREA REDESIGN CHANGE UNIT SIZES IRRIGATION RE-DO PARKING UPGRADE OFFICES CHANGE METERING	ESTIMATED COST
1-1	256,000	1,138,000	920,000	114,000	2,428,000
1-3 1-4 1-5 1-8	1,014,000 2,649,000 647,000 390,000	7,665,000 8,802,000 2,944,000 1,638,000	3,576,000 7,430,000 746,000 2,746,000	1,524,000 1,037,000 598,000 4,819,000	13,779,000 19,918,000 4,935,000 9,593,000 2,683,000 1,274,000
1-8 1-9 1-10 1-11	549,000 165,000 423,000 561,000	1,194,000 481,000 1,908,000 3,101,000	689,000 410,000 3,696,000	251,000 218,000 4,092,000	2,683,000 1,274,000 10,119,000 6,824,000
1-15 1-16 1-17A(E) 1-17A(W)	491,000 611,000 -0-	2,194,000 2,416,000 -0- 168,000	2,750,000 2,530,000 3,108,000 -0-	412,000 226,000 557,000 -0- -0-	5,441,000 6,692,000 -0-
1-178 1-18(1) 1-18(2)E	-0- 324,000 40,000 2,930,000	2,715,000 629,000 6,300,000	48,000 1,667,000 -0- 8,270,000	2,372,000 -0- 2,300,000	216,000 7,078,000 669,000 19,800,000
1-18(2)W 1-18(3) -18(4) 1-18(5)	3,430,000 384,000 146,000	293,000	9,350,000 483,000 5,623,000	2,530,000 257,000 240,000 -0-	22,300,000 1,417,000 7,529,000 -0-
1-18(6) 1-18(7) 1-18(7)A 1-18(10)	360,000 1,390,000 160,000 97,000	3,000	1,979,000 4,250,000 227,000	548,000 1,255,000 18,000 -0-	5,258,000 10,742,000 408,000 877,000
1-18(13) 1-19(1) 1-19(2) 1-20	40,000 85,000 45,000 47,000	557,000 250,000 725,000	-0- -0- -0- -0-	-0- -0- -0- -0-	597,000 335,000 770,000 479,000
1-21 1-23 1-27 1-28	78,000 34,000 100,000	353,000 105,000 602,000	-0- -0- 8,000	-0- -0- -0-	431,000 139,000 710,000
1-29 1-30 A 1-30 B	30,000 31,000 52,000 -0-	462,000	-0- -0- 18,000 -0-	-0- -0- -0- -0-	126,000 333,000 532,000 -0-
1-30 c 1-31 1-32 1-33	-0- 39,000 45,000 6,000	651,000	-0- -0- -0- 2,000	-0- 6,000 -0- -0-	-0- 372,000 696,000 12,000
1-34 1-34 1-34 1-35	5,000 23,000 23,000 14,000	81,000 156,000	18,000 14,000 18,000 3,000	3,000 -0- 16,000	56,000 118,000 213,000
1-35 1-35 1-36 1-37 1-39 A	20,000 24,000 95,000	172,000 24,000 38,000	10,000 -0- -0-	16,000 -0- -0-	99,000 218,000 48,000 133,000
1-39 B	35,000 10,000	39,000 70,000	6,000	-0-	80,000
TOTAL ESTIMATED COST	17,898,000	64,655,000	60,595,000	23,409,000	166,557,000



PROJECT: HOLLY COURTS C	AL 1-1		DATE: _	5/14/85	
OCCUPANCY: Families (few elderly) NUMBER OF UNITS: 118 HEX NUMBER OF BUILDINGS: 10 HO	TYPE OATING SOT WATE TILITY UMBER O	F ROOF: YSTEM: I R SYSTEM ARRANGEM F ELEVAT	ndividual I: Solar-C MENT: Indi ORS: 0	Console Central Bo ividual Me	oiler
IMPROVE	MENTS R	EQUIRED			
HEALTH AND SAFETY ITEMS Provide Second Means of Egress Apartment Smoke Detectors Pest Extermination Additional Exterior Lighting		18,000 24,000 12,000 59,000	213,000x2	20%= 256,	000
DETERIORATION REPAIRS Kitchen Flooring Kitchen Countertops and Cabinet De Apartment Painting Exterior Painting Tile for Tub Walls Upgrade Electrical System Upgrade One Hot Water Boiler Replace Signs Repair Fencing Leaks in Community Room	oors 2 1 1 1	18,000 36,000 77,000 18,000 18,000 5,000 12,000 36,000 10,000	948,000×2	20%=1,138,	000
ITEMS TO IMPROVE LIVEABILITY Provide Private Rear Yards Provide Forced Air Heating System Upgrade Landscaping Upgrade Play Areas Doors For Closets	2	36,000 36,000 18,000 59,000 18,000	767,000×2	20%= 920,	000
ITEMS TO IMPROVE MANAGEABILITY Provide Irrigation System	\$	95,000x2	20%= 114,0	000	
ESTIMATED COST OF REQUIRED IMPRO	VEMENTS	:	\$ 2.42	28.000	T

\$ 2,428,000

PROJECT: POTRERO TERRACE	CAL 1-2		DATE: 5/14/85
YEAR CONSTRUCTED: 1941 OCCUPANCY: Families NUMBER OF UNITS: 469 NUMBER OF BUILDINGS: 39 BUILDING TYPES: 2-1/2 Story BLDG CONSTRUCTION: Concrete SITE DESCRIPTION: 17.2 Steep Acres	TYPE OF HEATING HOT WAT UTILITY NUMBER	ROOF: SYSTEM ER SYSTI ARRNGEI OF ELEVI	SIVELY MODERNIZED: N/A Tile : Hot Water Boiler EM: Central Boiler MENT: Elec Check&Ind Gs ATORS: 0 DING/SPACE: Yes Sml
	VEMENTS	DECLITOR	
HEALTH AND SAFETY ITEMS Apartment Smoke Detectors Provide Second Means of Egress Pest Extermination Additional Exterior Lighting Gas Lines (funded)	\$	94,000 469,000 47,000 235,000	845,000x20%=1,014,000
DETERIORATION REPAIRS Major Boiler Repairs Thermostatic Control Valves Rpr Kitchen Cabinet Doors and S Replace Wood Windows (1/2 Proje Apartment Floors Apartment Painting Repair Wiring Repair Leaks From Balconies Soil Erosion Repair Fencing Repair Bathrooms - Tile Over Tu Exterior Electrical System Repair Doors and Locks	helves ct) 1,	355,000 188,000 938,000 469,000 704,000 469,000 100,000 300,000 141,000 469,000 469,000 285,000	6,387,000x20%=7,665,000
ITEMS TO IMPROVE LIVEABILITY Upgrade Landscaping Upgrade Play Areas Upgrade Parking Area Bedroom Closet Doors Convert to Individual Forced Ai Convert to Individual Water Hea Upgrade Building Public Areas	r H <b>eat</b> ters	469,000 235,000 300,000 469,000 938,000 469,000 100,000	2,980,000x20%=3,576,000
ITEMS TO IMPROVE MANAGEABILITY Upgrade Offices Reduce Number of One BR Units Provide Irrigation Convert to Individual Metering		10,000 200,000 375,000 685,000	1,270,000x20%=1,524,000

ESTIMATED COST OF REQUIRED IMPROVEMENTS: 13,779,000

	-				г	
P	ROJECT:	SUNNYDALE	CAL	1-3	DATE:	5/14/85
7	EAR CONS	TRUCTED: 1941	VEAR	COMPREHI	PNSTVELV N	10DERNIZED: N/A
		: Families		OF ROOF		ODERNIZED. N/A
		UNITS: 767				e Space Heaters
		TYPES: Town Houses				vidual Water Htrs
						heck Meters
		CONSTRUCTION: Concrete				
	DITE DESC.	RIPTION: 7.8 Sloping Ac	eres (	COMMUNITY	A BUILDING	S/SPACE: Yes
			EMEN'	rs requir	RED	
100g		D SAFETY ITEMS				
		oor Security	\$	460,000		
		Smoke Detectors		154,000		
		econd Means of Egress		772,000		
	Replace G			360,000		
		rmination		77,000		
1	Additiona	l Site Lighting	\$	384,000	2,207,000	x20% = 2,649,000
1	DETERIORA	TION REPAIRS				
	Repipe un		\$1	,600,000		
		ounter Tops	•	386,000		
	Electrica			767,000		
		nd Water lines Leak		300,000		
		abinet Doors and Shelve	es 1	,534,000		
		s Leaking		200,000		
		oil Erosion		100,000		
		dissing Signs		77,000		
		mmunity Space Doors & S	Stage	20,000		
		ooring and Electrical S				
		clone Fencing	2	230,000		
		lectric Check Meters		150,000		
		ablic Restrooms		5,000		
		Flooring	1	,151,000		
	Repair Wi	2		350,000		
		to Doors & Hardware	\$		7,335,000	x20% = 8,802,000
	TERMS TO	IMPROVE LIVEABILITY				
		ng System (Forced Air)	\$1	.534.000		
		Yards For Tenants		,534,000		
		Landscaping	_	767,000		
		Showers Over Tubs	1	,155,000		
		Closet Doors		767,000		
		Additional Recreation Eq	nuin			
		Public Laundry	4uip. \$	50,000	6.192.000	x20% = 7,430,000
	riovide r	dbile baundry	<del>-</del>	30,000	0,132,000	771307000
		IMPROVE MANAGEABILITY		614 606		
		on System	\$	614,000		
		Old Wash Houses		20,000		
		al Larger Units Needed		N/A		
	Stripe Pa	arking Lots		30,000	064 065	200 3 005 006
	Reduce th	ne Number of Small Units	\$	200,000	864,000	x20% = 1,037,000
	ЕСТИМАТЕ	ED COST OF REQUIRED IMPE	ROVEM	ENTS:	T	
	DOTTMIL	D CODI OF INDOURNED THE	+ 24.1.		\$ 19,	918,000



PROJECT: VALENCIA GARDENS	CAL 1-	4	DATE:	5/14/85
YEAR CONSTRUCTED: 1942 OCCUPANCY: Families NUMBER OF UNITS: 246 NUMBER OF BUILDINGS: 11 BUILDING TYPES: 3 Story BLDG CONSTRUCTION: Concrete SITE DESCRIPTION: 5 Flat Acres	TYPE OHEATINHOT WAUTILIT	F ROOF: G SYSTEM TER SYSTE Y ARRNGER OF ELEVE	Built-Up: Hot Wate EM: Solar MENT: Elec	&Centrl Boiler c Check Meters
IMPRO	VEMENTS	REQUIRE	D	
HEALTH AND SAFETY ITEMS Apartment Smoke Detectors Pest Extermination Fire Sprinkler System Gas Line Leaks	\$	50,000 25,000 263,000 200,000	538,000	0x20%=647,000
DETERIORATION REPAIRS Paint Public Stairs Apartment Painting Apartment Flooring Tile Bath Tub Walls Mail Boxes Repair Meeting Rooms Kitchen Cabinet Doors and Shelv Major Boiler Work Thermostatic Control Valves Upgrade Parking Lots Repair Fencing Upgrade Electrical System ITEMS TO IMPROVE LIVEABILITY Upgrade Play Equipment Closet Doors Upgrade Landscaping	res \$	130,000 246,000		0x20%=2,944,000 20%=746,000
ITEMS TO IMPROVE MANAGEABILITY Provide Irrigation System Reduce Number of One Bedroom Un	nits	\$198,000 \$300,000	498,000x	20%=598,000

ESTIMATED COST OF REQUIRED IMPROVEMENTS:

\$ 4,935,000



PROJECT: BERNAL DWELLINGS	CAL 1-5	DATE: 5/14/85
SITE DESCRIPTION: 1 Semi-Flat Block	TYPE OF ROOF: HEATING SYSTE HOT WATER SYS UTILITY ARRNO NUMBER OF ELE COMMUNITY BUI	CM: Forced Dir & Wall Htr GTEM: Indv WH & Cent Blr GEMENT: Elec Check Meters CVATORS: 1 ELDING/SPACE: Yes
IMPROV	EMENTS REQUIR	RED
HEALTH AND SAFETY ITEMS Apartment Smoke Detectors Fire Sprinkler System Emergency Exit Lighting Pest Extermination Additional Site Lighting	\$ 42,00 154,00 4,00 21,00 \$ 104,00	00
DETERIORATION REPAIRS Apartment Flooring Apartment Painting Upgrade Electrical System Paint Interior Public Areas Mail Boxes Upgrade Public Laundry Upgrade Meeting Rooms Repair Fencing Upgrade Boilers Highrise Building Garbage Chute Repair Windows Repair Doors and Locks	\$ 312,00 312,00 208,00 50,00 63,00 10,00 62,00 13,00 100,00 \$ 125,00	00 00 00 00 00 00 00
ITEMS TO IMPROVE LIVEABILITY Upgrade Play Areas Upgrade Landscaping Modernize Kitchens Provide Showers and Tile Tub Wall Closet Doors  ITEMS TO IMPROVE MANAGEABILITY Provide Irrigation System	\$ 208,00 \$ 166,00	00 00 00 2,288,000x20%=2,745,000
Reduce Number of 1 BR Units Relocate Public Stairs to Exters Convert Lwr HRise Floors to Walk Redo Parking Lots Redesign Highrise Entrance Lobby  ESTIMATED COST OF REQUIRED IMPRO	x-Ups 500,00 100,00 x \$ 50,00	00



PROJECT: WESTSIDE COURTS	CAL 1-8	DATE:	5/14/85
YEAR CONSTRUCTED: 1943 OCCUPANCY: Families & Elderly NUMBER OF UNITS: 136 NUMBER OF BUILDINGS: 6	YEAR COMPREH TYPE OF ROOF HEATING SYST HOT WATER SY UTILITY ARRAN NUMBER OF EL	ENSIVELY M : Built-U EM: Indv. STEM: Cent GEMENT:Gas EVATORS: 0	ODERNIZED: N/A p Wall Heaters ral Wtr Heaters & Elec. Ck.Mtr
IMPRO	VEMENTS REQUI	RED	
HEALTH AND SAFETY ITEMS Smoke Detectors In Units Fire Sprinkler System Pest Extermination Replace Exterior Gas Lines	28,0 145,0 14,0 270,0 457,0	00	549,000
DETERIORATION REPAIRS Upgrade Water Heaters Kitchen Cabinet Shelves, Doors, Interior Water Pipes Apartment Flooring Apartment Painting Repair Gabage Chute Doors Mailboxes Replace Medicine Cabinets	272,0 204,0 136,0 20,0 41,0 30,0	00 00 00 00 00 00	[1,194,000]
ITEMS TO IMPROVE LIVEABILITY Install Showers and Tile Walls Closet Doors Upgrade Play Areas Upgrade Landscaping Rehabilitate Community Spaces	204,0 136,0 68,0 136,0 30,0 574,0	00 00 00 00	[689,000]
ITEMS TO IMPROVE MANAGEABILITY Irrigation System Redo Parking Lots Secure Roofs	109,0 50,0 50,0 209,0	00	[251,000]
ESTIMATED COST OF REQUIRED IMP	ROVEMENTS:	\$ 2,	683,000




PROJECT:	WESTBROOK APARTMENTS	CAL 1-9		D	ATE:	5/14/85
OCCUPANCY NUMBER OF NUMBER OF BUILDING BUILDING	TRUCTED: 1956 : Families UNITS: 226 BUILDINGS: 37 TYPES:2 Story Twn.hse. CONSTRUCTION: Concrete RIPTION: 19.1 Steep Act	TYPE OF HEATING HOT WATH UTILITY NUMBER (	RC SY ER AF OF	OOF: Bu STEM: F SYSTEM: RANGEME ELEVATO	ilt-Up orced Indv. NT: Ir RS: 0	Air & Wall Htrs Water Heaters dividually Mtrd
	IMPRO	VEMENTS 1	REÇ	UIRED		
	D SAFETY ITEMS ecurity Window Grills I rmination	by Doors				000x20%= 165,000
Repair Fe Roofing Repair Co Remove Gr Repair La	mmunity Space afitti at Community Spa			68,000 113,000 10,000 10,000 100,000		00x20%=481,000
Upgrade S	IMPROVE LIVEABILITY Site Landscaping Play Equipment			226,000 115,000		00x20%=410,000
	IMPROVE MANAGEABILITY Errigation System		\$	181,000	x20%=2	18,000
ESTIMATE	ED COST OF REQUIRED IMP	ROVEMENT	s:	\$	1,27	4,000



PROJECT: POTRERO ANNEX	CAL 1-10 DATE: 5/14/85
YEAR CONSTRUCTED: 1955 OCCUPANCY: Families NUMBER OF UNITS: 137 NUMBER OF BUILDINGS: 23 BUILDING TYPES: 2-1/2 Story BLDG CONSTRUCTION: Wd Frame SITE DESCRIPTION: 9.2 Steep Acres	YEAR COMPREHENSIVELY MODERNIZED: N/A TYPE OF ROOF: Built-Up HEATING SYSTEM: Indv Wall Heaters HOT WATER SYSTEM: Central Water Htrs UTILITY ARRNGEMENT: Elec Check Meters NUMBER OF ELEVATORS: 0 COMMUNITY BUILDING/SPACE: Only Childer
IMPROV	VEMENTS REQUIRED
HEALTH AND SAFETY ITEMS Apartment Smoke Detectors Pest Extermination Additional Exterior Lighting Better Door and Window Security	\$ 28,000 14,000 60,000 \$ 250,000 352,000x20%=423,000
DETERIORATION REPAIRS Replace Water Pipes Replace Wood Windows Upgrade Electrical System Apartment Flooring Repair Fencing Interior Painting	\$ 420,000 280,000 350,000 210,000 50,000 \$ 280,000 1,590,000x20%=1,908,000
ITEMS TO IMPROVE LIVEABILITY Modernize Kitchens Install Showers and Wall Tile Convert to Forced Air Heating Convert to Individual Water Heat Provide Private Yards Upgrade Landscaping Upgrade Play Areas Provide Closet Doors	\$ 960,000 210,000 280,000 140,000 280,000 1,000,000 70,000 \$ 140,000 3,080,000x20%=3,696,000
ITEMS TO IMPROVE MANAGEABILITY Provide Irrigation Convert to Individual Metering Remv Wd Blcnies-Instl Fire Esca Reduce Number of 1 BR Units Improve or Remove Garden Apartm Mothball Non-rentable Isolated Provide Additional Site Fencing	ents } 200,000 Units}
ESTIMATED COST OF REQUIRED IMP	ROVEMENTS: \$ 10,119,000



PROJECT: NORTH BEACH C	CAL 1-11 DATE: 3/8/85	
YEAR CONSTRUCTED: 1952 Y	YEAR COMPREHENSIVELY MODERNIZED: N/	Α
	TYPE OF ROOF: Built-Up	
	HEATING SYSTEM: Steam Boilers	
	HOT WATER SYSTEM: Central Boiler	
	JTILITY ARRNGEMENT: Elec Check Mete	rs
	NUMBER OF ELEVATORS: 0	
	COMMUNITY BUILDING/SPACE: Yes	
Acres		
HEALTH AND SAFETY ITEMS	EMENTS REQUIRED	
	¢ 46 000	
Apartment Smoke Detectors	\$ 46,000	
Repl Wdw Grlls in Slpng Rms	40,000	
Fire Sprinkler System Needed	244,000	
Pest Extermination	23,000	
Additional Exterior Lighting	\$ 115,000 468,000x20%=561,000	
DETERIORATION REPAIRS		
	\$ 105 000	
Major Boiler Repairs	\$ 185,000	
Thermostatic Control Valves	92,000	
Bathroom Tub Walls	229,000	
Wood Windows In Poor Condition	458,000	
Repair Apartment Leak Damage	50,000	
Apartment Painting	345,000	
Apartment Flooring	345,000	
Mail Boxes	69,000	
Balcony Drains Get Stopped up	100,000	
Replace Signs	23,000	
Repair Fencing	69,000	
Bathrm Leaks from Toilets above	115,000	
	60,000	
Balcony-Wall Flashing		
Upgrade Electrical System	344,000	
Repair Structural Concrete Damage		000
Pave Parking Lots	\$ 60,000 2,584,000x20%=3,101,0	300
ITEMS TO IMPROVE LIVEABILITY		
Showers Over Tubs	\$ 115,000	
Upgrading of Landscapping	229,000	
Upgrade Play Areas	115,000	
Modernize Kitchens	1,603,000	
		000
Doors for Closets	$$229,000 2,291,000 \times 20 = 2.750,0$	300
ITEMS TO IMPROVE MANAGEABILITY		
Provide an Irrigation System	\$183,000	
Stripe Parking Lots	10,000	
Enclosures for Garbage Dumpsters	·	
znozobazob zoz bazwago bampo obzo		
		Т
ESTIMATED COST OF REQUIRED IMPRO	OVEMENTS: \$ 6,824,000	L




PROJECT: PING YUEN CAL 1-15 DATE: 5/14/85 YEAR CONSTRUCTED: 1952 YEAR COMPREHENSIVELY MODERNIZED: N/A OCCUPANCY: Families & Elderly TYPE OF ROOF: Built-Up NUMBER OF UNITS: 234 HEATING SYSTEM: Hot Water Boiler NUMBER OF BUILDINGS: 3 HOT WATER SYSTEM: Central Boiler BUILDING TYPES: 6 Story UTILITY ARRNGEMENT: Elec Check Meters BLDG CONSTRUCTION: Concrete NUMBER OF ELEVATORS: 4 SITE DESCRIPTION: 3 Sloping COMMUNITY BUILDING/SPACE: Yes Sites IMPROVEMENTS REQUIRED HEALTH AND SAFETY ITEMS Apartment Smoke Detectors 47,000 Replace Window Grills In Sleeping Rms 20,000 Emergency Exit Lighting 12,000 Repair Fire Exit Doors 56,000 Install Fire Sprinkler System 250,000 Pest Extermination 24,000  $409,000 \times 20\% = 491,000$ DETERIORATION REPAIRS Exterior Painting 234,000 Replace Wood Windows 468,000 Replace Missing Signs 24,000 Rehab Boilers 160,000 Thermostatic Control Valves 94,000 234,000 Interior Painting 145,000 Upgrade Apartment Doors 234,000 Apartment Flooring Upgrade Electrical System 235,000  $1.828.000 \times 20\% = 2.194.000$ ITEMS TO IMPROVE LIVEABILITY Modernize Kitchens 1,639,000 Ventilation For Kitchens 118,000 Showers Over Tubs Upgrade Play Areas 117,000 234,000 Provide Closet Doors  $2,108,000 \times 20\% = [2,530,000]$ ITEMS TO IMPROVE MANAGEABILITY 188,000 Provide Irrigation System  $188,000 \times 20\% =$ 226,000 ESTIMATED COST OF REQUIRED IMPROVEMENTS: 5,441,000



PROJECT: ALEMANY	CAL 1-1	.6	DATE:	5/14/85
YEAR CONSTRUCTED: 1955  OCCUPANCY: Families  NUMBER OF UNITS: 158  NUMBER OF BUILDINGS: 25  BUILDING TYPES: 2 & 3 Story  BUILDING CONSTRUCTION: Wood Fra  SITE DESCRIPTION: 9.8 Acres Slo	TYPE OF HEATING HOT WAT UTILITY	' ROOF: SYSTEM: 'ER SYST ' ARRANG CR OF EI	Built-Up Individual In	wal Wall Heaters . Water Htrs. heck Meters 0
IMPRO	VEMENTS	REQUIRE	ED	
Remove Fixed Grills in sleeping Apartment Smoke Detectors Pest Extermination Additional Exterior Lighting Provide Stair Railing Replace Gas Lines DETERIORATION REPAIRS Replace Windows Repair Flooring Repair Roof Leaks Water Heaters Repair Public Stairs and Balcor Repair Poors, Locks and Mail sl Remove Birds Under Roof Overhar Exterior Painting Replace Signs Address Serious Soil Erosion Repair Cyclone Fencing	\$ 3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	16,79,50, \$ 300, \$ 300, \$ 300, \$ 37,000, \$ 37,000, \$ 58,000, \$ 58,	000 000 000 000 000 509	0x20%=2,416,000
ITEMS TO IMPROVE LIVEABILITY Modernize Kitchens Provide Showers Upgrade Electrical System Replace Wall Heaters With Force Provide Public Laundry Upgrade Meeting Space Provide Private Yards Upgrade Landscaping Upgrade Play Areas Provide Closet Doors  ITEMS TO IMPROVE MANAGEABILITY Replace Hardwood Floors with Tre	2 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	207,000 237,000 258,000 316,000 50,000 10,000 816,000 80,000 258,000 337,00 127,00	00	0x20%=3,108,000 00x20%= 557,000




PROJECT: HUNTERS POINT A WEST	CAL 1-17 A	DATE:	3/8/85
OCCUPANCY: Families NUMBER OF UNITS: 133 NUMBER OF BUILDINGS: 17 BUILDING TYPES: 2 & 3 Story BUILDING CONSTRUCTION: Wood Frame SITE DESCRIPTION: Steep Sloping	TYPE OF RO HEATING SY HOT WATER UTILITY AR ME NUMBER O	OF: Built-Up STEM: Forced A SYSTEM: Indv. RANGEMENT: Ind F ELEVATORS: 0 BUILDING/SPACE	Water Hts. lividually Mtrd
HEALTH AND SAFETY ITEMS			
DETERIORATION REPAIRS Repair Irrigation System Repair Site Fencing Repair Play Equipment Remove Grafitti Exterior Painting of Selected Areas	\$ 10,000 10,000 50,000 20,000 \$ 50,000	140,000x20%	= 168,000
ITEMS TO IMPROVE LIVEABILITY Provide Additional Irrigation	\$ 40.000	40,000x20%= 4	8.000
ITEMS TO IMPROVE MANAGEABILITY	7 40,000	20,000 AZ0 6- 4	
ESTIMATED COST OF REQUIRED IMP	PROVEMENTS:	\$ 216,	000



PROJECT: HUNTERS POINT A EAST	CAL 1-17 A	DATE:	5/14/85
YEAR CONSTRUCTED: 1953 OCCUPANCY: Families NUMBER OF UNITS: 80 NUMBER OF BUILDINGS: 10 BUILDING TYPES: 2 & 3 Story BUILDING CONSTRUCTION: Wood Fra SITE DESCRIPTION: Steep Sloping	TYPE OF ROOF: HEATING SYSTE HOT WATER SYS UTILITY ARRAN	Built-Up M: Forced TEM: Indv. GEMENT: Ir LEVATORS:	Air/Wall Htrs Water Htrs adividually Mtro 0
IMPRO	OVEMENTS REQUIR	ED	
HEALTH AND SAFETY ITEMS			
DETERIORATION REPAIRS			
(O			
ITEMS TO IMPROVE LIVEABILITY			
ITEMS TO IMPROVE MANAGEABILITY			
FORTMARED COST OF PROHIPED IMP	DDOWEMENTS •	T	

NO FUNDS NEEDED



PROJECT: HUNTERS POINT B	CAT 1 17D	DAME.	2/0/05
TROOLET: INONIERS POINT B	CAL 1-17B	DATE:	3/8/85
YEAR CONSTRUCTED: 1959	YEAR COMPREH	ENSIVELY MO	DERNIZED: N/A
OCCUPANCY: Families	TYPE OF ROOF	Built-Up	
NUMBER OF UNITS: 82	HEATING SYSTE	EM: Indv Wa	11 Heaters
NUMBER OF BUILDINGS: 9	HOT WATER SYS	STEM: Bldg	Water Heaters
BUILDING TYPES: 2 & 3 Story	UTILITY ARRNO		
BLDG CONSTRUCTION: Wood Frame	NUMBER OF ELE	EVATORS: 0	
SITE DESCRIPTION: 7.6 Sloping	COMMUNITY BUI	LDING/SPAC	E: No
Acres			
IMPRO	VEMENTS REQUIE	RED	
HEALTH AND SAFETY ITEMS			
Apartment Smoke Detectors	\$ 20,00	10	
Exterior Lighting	100,00		
Door and Window Security			20%=324,000
DETERIORATION REPAIRS	9 130,00	270,0002	200-324,000
Repairs to Walls and Ceiling	\$ 240,00	0.0	
Windows	160,00		
Roofs	80,00		
Plumbing	250,00		
Apartment Flooring	246,00		
Apartment Painting	123,00		
Electrical	205,00		
Site Fencing	100,00		
Exterior Painting	82,00		
Mail Boxes	25,00		
Plumbing Fixtures	164,00		
Bathroom Accessories	41,00		
Kitchen Cabinets	246,00		
Site Gas System			$0 \times 20 = 2,715,000$
ITEMS TO IMPROVE LIVEABILITY			
Showers and Tile Over Tubs	\$ 123,00		
Provide Handicapped Units	100,00		
Closet Doors	82,00		
Upgrade Landscaping	820,00		
Private Yards	164,00		
Community Space	\$ 100,00	00 1,389,00	$0 \times 20 = 1,667,000$
ITEMS TO IMPROVE MANAGEABILITY			
Open Public Stairs	\$1,500,00		
Centralized Garbage Dumpsters	80,00		
Irrigation System	66,00		0000 272 000
Individual Gas & Electric Meter	s 330,00	1,9/6,00	$0 \times 20 = 2,372,000$
* Plans are almost completed t		\$ 7,0	78,000 *

\* Plans are almost completed to lease this \$ 7,078,000 project to a private developer for the required rehabilitation work and future management. No Authority funds should be therefore required for this project.




PROJECT: 2451 SACRAMENTO ST.	CAL 1-18(1) DATE: 5/14/85					
YEAR CONSTRUCTED: 1966 OCCUPANCY: Elderly NUMBER OF UNITS: 98 NUMBER OF BUILDINGS: 1 BUILDING TYPES: 11 Story BUILDING CONSTRUCTION: Concre SITE DESCRIPTION: Sloping	YEAR COMPREHENSIVELY MODERNIZED: N/A TYPE OF ROOF: Built-Up HEATING SYSTEM: Hot Water Boiler HOT WATER SYSTEM: Central Boiler UTILITY ARRANGEMENT: Master Metered NUMBER OF ELEVATORS: 2 COMMUNITY BUILDING/SPACE: Yes					
IMPROVEMENTS REQUIRED						
HEALTH AND SAFETY ITEMS Apartment Smoke Detectors Emergency Exit Lighting Pest Extermination	\$ 20,000 3,000 \$ 10,000 33,000x20%=40,000					
DETERIORATION REPAIRS Major Plumbing Problems Apartment Painting Project Entrance Door Rear Fence In Need of Repair Elevator Emergency Phones Major Boiler Work Thermostatic Control Valves	\$ 294,000 147,000 1,000 5,000 2,000 35,000 40,000u 524,000x20%=629,000					

### ITEMS TO IMPROVE LIVEABILITY

### ITEMS TO IMPROVE MANAGEABILITY

ESTIMATED	COST	OF	REQUIRED	IMPROVEMENTS:	\$ 669,000



```
PROJECT: YERBA BUENA PLAZA EAST CAL 1-18(2)
                                                 DATE:
YEAR CONSTRUCTED: 1956
                                 YEAR COMPREHENSIVELY MODERNIZED:
OCCUPANCY: Families & Elderly
                                TYPE OF ROOF: Built-Up
NUMBER OF UNITS: 276
                                HEATING SYSTEM: Hot Water Boiler
NUMBER OF BUILDINGS: 11 HOT WATER SYSTEM: Central Boiler
BUILDING TYPES: 3,6,&11 Stories UTILITY ARRANGEMENT: Elect.Chck.Mtrs.
BUILDING CONSTRUCTION: Concrete NUMBER OF ELEVATORS: 5
SITE DESCRIPTION: Flat & Sloping COMMUNITY BUILDING/SPACE: Yes
                          IMPROVEMENTS REQUIRED
HEALTH AND SAFETY ITEMS
Complete Fire Sprinkler System $
                                     375,000
Apartment Smoke Detectors
                                      50,000
Emergency Exit Lighting
                                      15,000
Earthquake Work
                                   1,050,000
Door and Window Security
                                     500,000
Exterior Lighting
                                     76,000
Modify Fire Escapes Per Code
                                     145,000
Remove Asbestos
                                     200,000
Pest Extermination
                                      30,000 2,441,000x20%=2,930,000
DETERIORATION REPAIRS
Replace Boilers
                                    $1,000,000
New Windows
                                       570,000
Rehab Elevators
                                       570,000
New Piping, Plmbg. Fixtures, Rpr. Leaks 1,500,000
Apartment Flooring
                                       415,000
                                       415,000
Apartment Painting
                                        85,000
Mail Boxes
New Garbage Chutes
                                       345,000
                                    $ 350,000 5,250,000x20%=6,300,000
Exterior Painting
ITEMS TO IMPROVE LIVEABILITY
Modernize Kitchens
                                         $2,040,000
Showers and Tile Over Tubs
                                            485,000
Provide Handicapped Units & Circulation
                                            140,000
                                            310,000
Closet Doors
                                            250,000
Upgrade Play Equipment
                                            290,000
Upgrade Landscaping
                                            559,000
Private Yards
                                            248,000
Upgrade Laundry
                                             85,000
Mail Boxes
                                          1,700,000
Upgrade Electrical System
                                            725,000
Provide Bay Windows
Upgrade Community Spaces
                                          58,000
                                          6,899,000x20%=8,270,000
ITEMS TO IMPROVE MANAGEABILITY
                                                  100,000
Reduce Number of 1 BR Units
Close Off Upr Fl.Corr./Seal Grn.Fl.Stor.Areas
                                                  168,000
                                                   72,000
Provide Resident Manager Units
                                                  646,000
Conv.HR. Lwr.Fl.to Wlk.Ups/Prvd.Lobbies to HR.
                                                  85,000
 Site Fencing
                                                  235,000
Provide Irrigation System
                                                  495,000
 Open 3 Story Public Stairs
                                                   .95,000
 Redo Parking Areas
                                                  20,000
 Upgrade Office Space
                                                1,916,000x20%=2,300,000
 ESTIMATED COST OF REQUIRED IMPROVEMENTS: | 19,800,000 |
```




PROJECT: YERBA BUENA PLAZA WEST CAL 1-18(2)	DATE: 5/14/85
OCCUPANCY: Families TYPE OF ROOF: NUMBER OF UNITS: 332 HEATING SYSTEM NUMBER OF BUILDINGS: 18 (connected) HOT WATER BUILDING TYPES: 3 & 11 Stories UTILITY ARRANG BUILDING CONSTRUCTION: Concrete NUMBER OF ELEV SITE DESCRIPTION: 1 3/4 sloping Blocks COMMUNITATION: IMPROVEMENTS REQUIRE	VATORS: 6 ITY BLDG./SPACE: Bsmt Sp
HEALTH AND SAFETY ITEMS  Complete Fire Sprinkler System \$ 450,000  Apartment Smoke Detectors 60,000  Emergency Exit Lighting 20,000  Modify Fire Escapes Per Code 175,000  Earthquake Work 1,265,000  Door and Window Security 600,000  Remove Asbestos 250,000	
Pest Extermination \$ 35,000	2,855,000x20%=3,430,000
DETERIORATION REPAIRS Replace Boilers \$1,150,000 New Windows 670,000 Rehab Elevators 640,000 New Piping, Plmbg. Fixtures, Rpr. Leaks 1,500,000 Apartment Flooring 500,000 Apartment Painting 500,000 New Garbage Chutes 416,000	
ITEMS TO IMPROVE LIVEABILITY  Modernize Kitchens \$2,300,000 Showers and Tile Over Tubs 500,000 Provide Hdcp. Units & Circulation 147,000 Closet Doors 570,000 Upgrade Play Equipment 270,000 Upgrade Landscaping 300,000 Private Yards 664,000 Upgrade Laundry 248,000 Upgrade Electrical System 1,883,000 Provide Community Spaces 58,000	5,826,000x20=6,990,000
Provide Bay Windows  ITEMS TO IMPROVE MANAGEABILITY  Reduce Number of 1 BR Units  Close off Upp.Fl.Corr./Seal Grn.Fl.Stor.Areas	7,792,000x20%=9,350,000 \$ 200,000 200,000
Provide Resident Manager Units Cvrt HR.Low.Fl.to Walk-ups/Prov.Lobbies for HI Site Fencing Provide Irrigation System Open 3 Story Public Stairs Redo Parking Areas Provide Office Space	100,000 130,000 578,000 105,000 20,000
	$2,109,000 \times 20\% = 2,530,000$

<sup>\*</sup> Funds have been requested from HUD to pursue this work. Should HUD determine the work too costly, replacement of the project with new units will be explored.



PROJECT:	HUNTERS VIEW	CAL	1-18(3)	DATE:	3/8/85
OCCUPANCY NUMBER OF NUMBER OF BUILDING BUILDING	TRUCTED: 1957 : Families UNITS: 267 BUILDINGS: 51 TYPES: 2 & 3 St CONSTRUCTION: V RIPTION: 22.45	TYPE HEAT HOT OTY UTIL	OF ROOF: ING SYSTEM WATER SYST ITY ARRANG MBER OF EI	Built-Up i: Forced TEM: Indv GEMENT: In EVATORS:	Air & Wall Htrs . Water Heaters ndividually Mtro 0
		IMPROVEMEN	TS REQUIRE	<u>ED</u>	
Provide S	D SAFETY ITEMS ecurity Window by Doors		\$320,000	)x20%=384	,000
Repair Fe		?	\$ 80,000 134,000 30,000	)	0x20%=293,000
Upgrade S	IMPROVE LIVEAB Site Landscapin Play Equipment		\$ 267,000 135,000		x20%=483,000
	IMPROVE MANAGE Irrigation Syst		\$214,000	)x20%=257	,000
ESTIMAT	ED COST OF REQU	IRED IMPROVEM	ENTS:	\$ 1,4	417,000



	T T						
PROJECT:	ALICE GRIFFITH	C	CAL 1-18 (4	1)	DATE:	5/14/85	
OCCUPANCY NUMBER OF NUMBER OF BUILDING BUILDING	TRUCTED: 1962 : Families UNITS: 258 BUILDINGS: 34 TYPES: 2 Story CONSTRUCTION: Wood Fr RIPTION: 24.8 Acres	I H	YPE OF ROME OF	OOF: SYS RRAN OF E	Built-Up M: Hot Wa TEM: Cent: GEMENT: Cl	ter Boiler ral Boiler heck Metere 0	N/A d
	IMPR	OVE	EMENTS REG	QUIR	ED		
Pest Exte Apartment Remove Wi	D SAFETY ITEMS rmination Smoke Detectors ndow Grills in g Rooms s Lines (funded)	\$	26,000 52,000 44,000	122	,000x20%=	146,000	
Repair Ro Thermosta Address S Repair Fe Repair "Wi Apartment Apartment	tic Control Valves oil Erosion Problems encing		129,000 37,000 100,000 100,000 100,000 387,000 387,000 26,000	1,2	66,000x20s	%= 1,520,00	<u>0</u>
Modernize Provide S Upgrade I Upgrade I Develop I Convert I Convert t Doors for Upgrade I Provide S ITEMS TO	IMPROVE LIVEABILITY  E Kitchens Showers Over Tubs Landscaping Play Areas Private Yards To Forced Air Heating To Indiv. Water Heater To Closets Electrical System Space-Child Care Cntr. IMPROVE MANAGEABILITY Thount of Large Units	S	1,806,000 387,000 258,000 129,000 516,000 516,000 258,000 258,000 258,000 258,000 258,000 258,000 200,000		686,000x20 = 240,000	0%= 5,623,0	00

ESTIMATED COST OF REQUIRED IMPROVEMENTS:

\$ 7,529,000




		т	
PROJECT: ROSA PARKS	CAL 1-18(5)	DATE:	5/14/85
YEAR CONSTRUCTED: 1961 OCCUPANCY: Elderly NUMBER OF UNITS: 198 NUMBER OF BUILDINGS: 1 BUILDING TYPES: 11 Story BLDG CONSTRUCTION: Concrete SITE DESCRIPTION: Flat	TYPE OF ROOF HEATING SYST HOT WATER SY	: Built-Up EM: Hot Wat STEM: Centr GEMENT: Ele EVATORS: 3	er Boiler alized Wtr Htr c Check Meters
IMPRO	VEMENTS REQUI	RED	
HEALTH AND SAFETY ITEMS			
DETERIORATION REPAIRS			
ITEMS TO IMPROVE LIVEABILITY			
ITEMS TO IMPROVE MANAGEABILITY			
ESTIMATED COST OF REQUIRED IM	PROVEMENTS:		INC NEEDED

NO FUNDS NEEDED



T				
PROJECT: PING YUEN NORTH	CAL 1-1	18(6)	DATE:	5/14/85
YEAR CONSTRUCTED: 1961 OCCUPANCY: Families & Elderly NUMBER OF UNITS: 194 NUMBER OF BUILDINGS: 1 BUILDING TYPES: 3 Story BLDG CONSTRUCTION: Concrete SITE DESCRIPTION: 1.4 Sloping Acres	TYPE OF HEATING HOT WAT UTILITY NUMBER COMMUNI	F ROOF S SYST TER SY 7 ARRN OF EL TY BU	: Built-I EM: Hot Wa STEM: Cen GEMENT: E EVATORS: C ILDING/SPA	ater Boiler tral Boiler lec Check Meters
IMPRO	OVEMENTS	REQUI	RED	
HEALTH AND SAFETY ITEMS Apartment Smoke Detectors Replace Window Grills in Sleeping Rooms Emergency Exit Lighting Repair Fire Exit Doors Install Fire Sprinkler System Pest Extermination  DETERIORATION REPAIRS Apartment Flooring Apartment Metal Entrance Doors Exterior Painting Bathtub Walls Bathroom Leaks From Toilets Abore Reputty Windows Mailboxes Rehab Elevators Repair Parking Lot Gates Apartment Painting Replace Missing Signs Major Boiler Work Thermostatic Control Valves Redesign Garbage Chute	ove	291,0 36,0 194,0 194,0 100,0 100,0 59,0 300,0 60,0 291,0 20,0 53,0 78,0	00 00 00 00 00 00 00 00 00 00 00 00 00	
	1,	,976,0	00 x 20% =	2,371,000
ITEMS TO IMPROVE LIVEABILITY New Showers Over Tubs Modernize Kitchens Bedroom Closet Doors		97,0 ,358,0 194,0 ,649,0	00	= [1,979,000]
ITEMS TO IMPROVE MANAGEABILITY Convert Roof Laundry to Apartme Provide Irrigation System	ents	300,0 156,0 456,0	00	= [548,000]
ESTIMATED COST OF REQUIRED IMP	PROVEMENT	rs:	\$ 5	,258,000



NORTH &	
	1-18(7) DATE: 5/14/85
OCCUPANCY: Elderly & Families  NUMBER OF UNITS: 306  NUMBER OF BUILDINGS: 18  BUILDING TYPES: 3 Story  BLDG CONSTRUCTION: Wood Frame  NUMBER OF BUILDING NUMBER OF BUILDING TYPES: 3 Story	COMPREHENSIVELY MODERNIZED: N/A  OF ROOF: Shingles ING SYSTEM: Hot Water Boiler WATER SYSTEM: Central Boiler ITY ARRNGEMENT: Elec Check Meters ER OF ELEVATORS: 0 UNITY BUILDING/SPACE: Convt Unit
HEALTH AND SAFETY ITEMS Fire Sprinkler System Apartment Smoke Detectors Door & Window Security Exterior Lighting Remove Window Grills in Sleeping Rms Pest Extermination	\$ 320,000 65,000 550,000 155,000 36,000 \$ 32,000 1,158,000x20%=1,390,000
DETERIORATION REPAIRS Major Boiler Work Thermostatic Control Valves Apartment Flooring Apartment Painting Repair Garbage Chute Doors Repair Sewer Lines Repair Gas Lines Reprir Ext. Walls, Stairs & Balconies Exterior Painting Mail Boxes (provided) Repair Windows Repair Roof Down Spouts Replace Signs	\$ 210,000 130,000 460,000 460,000 50,000 100,000 100,000 300,000 300,000 615,000 100,000 31,000
Soil Erosion Repair Waste Lines	50,000 \$ 300,000 3,206,000×20%=3,847,000
ITEMS TO IMPROVE LIVEABILITY  Modernize Kitchens Showers and Tile Wall Over Tubs Closet Doors Upgrade Play Equipment Upgrade Landscaping Upgrade Community Space Upgrade Electrical System  ITEMS TO IMPROVE MANAGEABILITY Reduce Number of Small Units	2,145,000 306,000 306,000 153,000 306,000 20,000 306,000 3,542,000x20%=4,250,000
Site Fencing Irrigation System Redo Parking Areas	200,000 245,000 \$ 200,000 1,045,000x20%=1,255,000
ESTIMATED COST OF REQUIRED IMPROVEMENT	ENTS: \$ 10,742,000



PROJECT: SUNNYDALE ANNEX CAL 1-18(7) A DATE: 5/14/85
YEAR CONSTRUCTED: 1962  YEAR COMPREHENSIVELY MODERNIZED: N/A OCCUPANCY: Elderly (few families) TYPE OF ROOF: Shingles NUMBER OF UNITS: 18  HEATING SYSTEM: Hot Water Boiler NUMBER OF BUILDINGS: 2  HOT WATER SYSTEM: Central Boiler BUILDING TYPES: 2 Story Walk-up UTILITY ARRANGEMENT: Elect.Check Mtrs BUILDING CONSTRUCTION: Wood Frame NUMBER OF ELEVATORS: 0 SITE DESCRIPTION: Flat  COMMUNITY BUILDING/SPACE: NO
IMPROVEMENTS REQUIRED
HEALTH AND SAFETY ITEMS  Pest Extermination \$ 2,000  Apartment Smoke Detectors 4,000  Provide Fencing for Security 100,000  Additional Exterior Lighting 9,000  Fire Sprinkler System \$ 18,000 133,000x20%=160,000
DETERIORATION REPAIRS Replace Missing Signs \$ 2,000x20%= 3,000
ITEMS TO IMPROVE LIVEABILITY Modernize Kitchens \$126,000 Upgrade Landscaping 18,000 Provide Showers Over Tubs 27,000 Provide Closet Doors \$18,000 189,000x20%=227,000
ITEMS TO IMPROVE MANAGEABILITY Provide an Irrigation System \$ 15,000x20%=18,000
ESTIMATED COST OF REQUIRED IMPROVEMENTS: \$ 408,000




	1			<del></del>				
PROJECT:	255 WOODSIDE AVE		CAL	1-18	(10)	DATE:	5/14/85	
OCCUPANCY NUMBER OF NUMBER OF BUILDING BUILDING	TRUCTED: 1968 : Elderly UNITS: 110 BUILDINGS: 1 TYPES: 10 Story CONSTRUCTION: Con	crete	TYP: HEA' HOT UTI: NUM	E OF ING WATE LITY BER O	ROOF: SYSTI R SYS ARRAI F ELI	Built- EM: Hot W STEM: Cen GEMENT:	ater Boiler tral Boiler Elect.Check 2	N/A Mtrs
		IMPROV	EME	NTS R	EQUII	RED		
Apartment Emergency	D SAFETY ITEMS Smoke Detectors Exit Lighting ermination Lighting	\$	33 11	,000 ,000 ,000	\$81	,000x20%=	\$97,000	
Major Boi Windows Door Lock Roof Leak Wall Leak Door Clos Paint Mee Paint Lav	CS CS		\$		000 000 000 000 000	650,000x	20%=780,000	
ITEMS TO	IMPROVE LIVEABIL	TY						

#### ITEMS TO IMPROVE MANAGEABILITY

ESTIMATED COST OF REQUIRED IMPROVEMENTS:

\$ 877,000



PROJECT: MISSION DOLORES		CAL 1-18	(13)	DATE:	5/14/85	
YEAR CONSTRUCTED: 1966 OCCUPANCY: Elderly NUMBER OF UNITS: 92 NUMBER OF BUILDINGS: 1 BUILDING TYPES: 10 Story BUILDING CONSTRUCTION: Concrete SITE DESCRIPTION: Flat	te	YEAR COMPREHENSIVELY MODERNIZED: N/A TYPE OF ROOF: Built-Up HEATING SYSTEM: Hot Water Boiler HOT WATER SYSTEM: Central Boiler UTILITY ARRANGEMENT: Elect.Check Mtrs NUMBER OF ELEVATORS: 2 COMMUNITY BUILDING/SPACE: Yes				
IMPI	ROV	EMENTS R	EQUIR	ED		
HEALTH AND SAFETY ITEMS Apartment Smoke Detectors Emergency Exit Lighting Pest Control	\$	19,000 5,000 9,000	33,0	00x20%= 40	,000	
DETERIORATION REPAIRS Apartment Window Leaks Apartment Painting Major Boiler Work Social Room Stove Apartment Stoves Thermostatic Control Valves Upgrade interior water system		184,000 92,000 40,000 1,000 50,000 37,000 50,000	464,	000×20%= 5	57,000	

### ITEMS TO IMPROVE LIVEABILITY

#### ITEMS TO IMPROVE MANAGEABILITY

ESTIMATED COST OF REQUIRED IMPROVEMENTS:

\$ 597,000



PROJECT:	990 PACIFIC AVE.	С	AL 1-19(1	L)	DATE:	5/14/85	
YEAR CONSTRUCTED: 1969 OCCUPANCY: Elderly NUMBER OF UNITS: 92 NUMBER OF BUILDINGS: 1 BUILDING TYPES: 7 Story BUILDING CONSTRUCTION: Concrete SITE DESCRIPTION: Corner Lot			YPE OF ROEATING SYOT WATER TILITY APUMBER OF	OOF: SYS RAN ELI	ENSIVELY MO Built-Up EM: Hot Wat STEM: Centr NGEMENT: E1 EVATORS: 2 ILDING/SPAC	er Boiler al Boiler ect.Check	N/A Mtrs.
	IMPRO	OVE	MENTS REC	QUII	RED		
Apartment Emergency	D SAFETY ITEMS Smoke Detectors Exit Lighting 1 Exterior Lighting		19,000 4,000 48,000	71	,000x20%=85	,000	
Major Boi New Roof Exterior		\$	33,000 46,000 92,000 37,000	208	3,000x20%=2	50,000	

## ITEMS TO IMPROVE LIVEABILITY

#### ITEMS TO IMPROVE MANAGEABILITY

ESTIMATED COST OF REQUIRED IMPROVEMENTS:

\$ 335,000



	T						
PROJECT:	1750 MCALLISTER	CAL	1-19	(2)	DATE:	5/14/85	
OCCUPANCY NUMBER OF NUMBER OF BUILDING BUILDING	TRUCTED: 1974 : Elderly UNITS: 97 BUILDINGS: 1 TYPES: 12 Story CONSTRUCTION: Concrete RIPTION: Slight Slope	TYPE HEAT HOT UTITE NUMBE	E OF BUILDING SER OF	ROOF: SYSTEM R SYST ARRANG F ELEV	Built-Up M: Hot Wat TEM: Centr GEMENT: Ma	er Boiler al Boiler ster Meter	N/A
	IMPR	OVEMEN	NTS RI	EQUIRE	ED		
Apartment Emergency	D SAFETY ITEMS Smoke Detectors Exit Lighting ermination		0,000 7,000 0,000	37,0	000x20=45,	000	
Building Apartment Major Boi Painting Parking I	Public Area Window Le Sliding Glass Doors Ler Work For Public Halls Lot Gate Needed Atic Control Valves		9° 285 63 20	0,000 7,000 5,000 3,000 0,000 9,000	604,000x	20%=725,00	<u>0</u>
ITEMS TO	IMPROVE LIVEABILITY						
ITEMS TO	IMPROVE MANAGEABILITY						

\$ 770,000

ESTIMATED COST OF REQUIRED IMPROVEMENTS:



•					
PROJECT:	3850-18TH STREET	CAL 1-2	20	DATE:	3/8/85
OCCUPANCY NUMBER OF NUMBER OF BUILDING 'BLDG CONS'	FRUCTED: 1970 : Elderly UNITS: 107 BUILDINGS: 5 FYPES: 3 to 5 Stories FRUCTION: Concrete RIPTION: Sloping Front - Back	TYPE OF HEATING HOT WAT UTILITY NUMBER	'ROOF: SYSTEM TER SYST ARRNGE OF ELEV	Built-Wall: Hot Wall: Sola	ater Boiler ar&Centrl Boiler Master Metered 2
	IMPRO	VEMENTS	REQUIRE	<u>D</u>	
Apartment	D SAFETY ITEMS Smoke Detectors Exit Lighting rmination	\$ \$	22,000 6,000 11,000		x20%=47,000
Public Ha Ventilati Paint Bas Major Boi Paint Pub Roof Leak Intercom Door Clos Kitchen S Bathroom	ement ler Work	Ş	15,000 54,000 10,000 51,000 54,000 5,000 10,000 54,000 54,000 43,000		0x20%=432,000
	IMPROVE LIVEABILITY  IMPROVE MANAGEABILITY				
ESTIMATE	ED COST OF REQUIRED IMP	ROVEMENT	rs:	\$ 4	79,000



PROJECT: 320-330 CLEMENTINA	CAL 1-21	DATE:	3/8/85
YEAR CONSTRUCTED: 1971 OCCUPANCY: Elderly NUMBER OF UNITS: 276 NUMBER OF BUILDINGS: 2 BUILDING TYPES: 13 Story BLDG CONSTRUCTION: Concrete SITE DESCRIPTION: Flat	YEAR COMPREHENTYPE OF ROOF: HEATING SYSTEM HOT WATER SYST UTILITY ARRNGENUMBER OF ELEV COMMUNITY BUIL	Built-Up 4: Hot Wat FEM: Centr EMENT: Ele VATORS: 4	er Boiler al Boiler c Check Meters
IMPRO	OVEMENTS REQUIRE	ED	
HEALTH AND SAFETY ITEMS Apartment Smoke Detectors Emergency Exit Lighting	\$ 56,000 9,000		20%=78,000
DETERIORATION REPAIRS Major Boiler Repairs Roof Repairs Thermostatic Control Valves	\$ 33,000 150,000 \$111,000	)	20%=353,000
ITEMS TO IMPROVE LIVEABILITY			
ITEMS TO IMPROVE MANAGEABILITY			
ESTIMATED COST OF REQUIRED IM	PROVEMENTS:	\$ 431	,000



•	T		Т	
PROJECT:	1880 PINE STREET	CAL 1-23	DATE:	3/8/85
OCCUPANCY NUMBER OF NUMBER OF BUILDING BLDG CONS	TRUCTED: 1973 : Elderly : UNITS: 113 : BUILDINGS: 1 : TYPES: 11 Story : TRUCTION: Concrete : RIPTION: Slopes Front to Back IMPRO	YEAR COMPREHE TYPE OF ROOF HEATING SYSTE HOT WATER SYS UTILITY ARRNO NUMBER OF ELE COMMUNITY BU	EM: Built-Up EM: Hot Wat STEM: Centr GEMENT: Ma EVATORS: 2 ILDING/SPAC	er Boiler al Boiler ster Metered
בי אור אויי אויי	ID SAFETY ITEMS			
Apartment	Smoke Detectors Exit Lighting	\$23,00 \$ 5,00		20%=34,000
Major Boi	ATION REPAIRS iler Work atic Control Valves	\$41,0 46,0		20%=105,000
140				
ITEMS TO	IMPROVE LIVEABILITY			
ITEMS TO	IMPROVE MANAGEABILITY			
ESTIMAT	ED COST OF REQUIRED IM	PROVEMENTS:	\$ 139	,000
			Y 100	,



PROJECT: 350 ELLIS STREET	CAL 1-27 DATE: 5/14/85
YEAR CONSTRUCTED: 1970 OCCUPANCY: Elderly NUMBER OF UNITS: 96 NUMBER OF BUILDINGS: 1 BUILDING TYPES: 13 Story BLDG CONSTRUCTION: Concrete SITE DESCRIPTION: Flat	YEAR COMPREHENSIVELY MODERNIZED: N/A TYPE OF ROOF: Built-Up HEATING SYSTEM: Hot Water Boiler HOT WATER SYSTEM: Central Boiler UTILITY ARRNGEMENT: Elect Check Meters NUMBER OF ELEVATORS: 2 COMMUNITY BUILDING/SPACE: Yes
IMPRO	OVEMENTS REQUIRED
HEALTH AND SAFETY ITEMS Apartment Smoke Detectors Emergency Exit Lighting Pest Extermination Site Lighting	\$ 20,000 5,000 10,000 \$ 48,000 83,000x20%=100,000
DETERIORATION REPAIRS Window Leaks (funded) Apartment Painting Meeting Room Ceiling Leaks Elevator Repair Needed Exterior Painting Major Boiler Work Public Halls Needed Painting Toilet Flush Valves Intercom Parking Lot Paving Public Restrooms Thermostatic Control Valves	\$ 144,000 5,000 80,000 96,000 42,000 50,000 10,000 20,000 10,000 \$ 39,000 501,000x20%=602,000
ITEMS TO IMPROVE LIVEABILITY Floor Numbers at Elevator Lobbi Public Laundry too Small	\$ 1,000 \$ 5,000 6,000x20%=8,000

# ITEMS TO IMPROVE MANAGEABILITY

ESTIMATED	COST	OF	REQUIRED	IMPROVEMENTS:	c	710 000
					\$	710,000



PROJECT: 666 ELLIS STREET	CAL 1-28	DATE:	3/8/85
YEAR CONSTRUCTED: 1971 OCCUPANCY: Elderly NUMBER OF UNITS: 100 NUMBER OF BUILDINGS: 1 BUILDING TYPES: 13 Story BLDG CONSTRUCTION: Concrete SITE DESCRIPTION: Flat	YEAR COMPREHITYPE OF ROOF HEATING SYSTIHOT WATER SYSUTILITY ARRNOW NUMBER OF ELICOMMUNITY BUT	Built-Up EM: Hot Wate STEM: Centr GEMENT: Mas EVATORS: 2	ral Boiler ster Metered
IMPRO	VEMENTS REQUII	RED	
HEALTH AND SAFETY ITEMS Apartment Smoke Detectors Emergency Exit Lighting	\$ 20,00 5,00	00 00 25,000x20	%=30 <b>,0</b> 00
DETERIORATION REPAIRS Major Boiler Work Flooring In Meeting Room Thermostatic Control Valves	\$ 35,00 5,00 40,00		)%=96,000
, re			
ITEMS TO IMPROVE LIVEABILITY			
ITEMS TO IMPROVE MANAGEABILITY			

\$ 126,000

ESTIMATED COST OF REQUIRED IMPROVEMENTS:



PROJECT: 345 ARGUELLO BLVD.	CAL 1-29 DATE: 3/8	/85			
YEAR CONSTRUCTED: 1973 OCCUPANCY: Elderly NUMBER OF UNITS: 69 NUMBER OF BUILDINGS: 1 BUILDING TYPES: 5 Story BUILDING CONSTRUCTION: Wood Fra SITE DESCRIPTION: Flat	TYPE OF ROOF: Built-Up  69 HEATING SYSTEM: Hot Water Boiler NGS: 1 HOT WATER SYSTEM: Central Boiler  5 Story UTILITY ARRANGEMENT: Master Metere  CTION: Wood Frame NUMBER OF ELEVATORS: 2				
IMPRO	VEMENTS REQUIRED				
HEALTH AND SAFETY ITEMS Apartment Smoke Detectors Emergency Exit Lighting Pest Extermination	\$ 14,000 5,000 \$ 7,000 26,000x20%=31,000	_			
DETERIORATION REPAIRS Roof Leaks Light Switches Garbage Disposals Closet Folding Doors Boiler Repairs Paint Front of Building Thermostatic Heaters Control Needed	\$ 35,000 36,000 35,000 69,000 39,000 10,000 \$ 28,000 252,000x20%=302,	000			
ITEMS TO IMPROVE LIVEABILITY					
ITEMS TO IMPROVE MANAGEABILITY					
ESTIMATED COST OF REQUIRED IM	PROVEMENTS: \$ 333,000				

\$ 333,000



PROJECT: 345 HERMAN STREET	CAL 1-30	A	DATE: _	3/8/85
YEAR CONSTRUCTED: 1971 OCCUPANCY: Elderly NUMBER OF UNITS: 42 NUMBER OF BUILDINGS: 1 BUILDING TYPES: 6 Story BUILDING CONSTRUCTION: Wood Frame SITE DESCRIPTION: Flat	TYPE OF HEATING HOT WATH UTILITY	ROOF: B SYSTEM: ER SYSTEM ARRANGEM	uilt-Up Hot Wate : Centra ENT: Ele ATORS: 1	
IMPROV	VEMENTS I	REQUIRED		
HEALTH AND SAFETY ITEMS Apartment Smoke Detectors Emergency Exit Lighting Pest Extermination Exterior Lighting Install Entrance Gate at Sidewa	\$ 1k <u>\$</u>	10,000 3,000 4,000 21,000 5,000		0x20%= 52,000
DETERIORATION REPAIRS Window Leaks Apartment Flooring (Carpeting) Apartment Painting Exterior Wall Leaks Roofing Leaks Office Painting Elevator Repairs Needed Halls Need Painting Exterior Painting Exterior Painting Reinstall Fans in Public Restroepaint Meeting Room Boiler Repairs Thermostatic Control Valves	\$ Oms	84,000 68,000 63,000 10,000 25,000 5,000 10,000 45,000 3,000 3,000 42,000 17,000		000x20%=462,000
ITEMS TO IMPROVE LIVEABILITY Better Garage Lighting Signs to Mark Floors in Stairwe	\$	10,000		0x20%=18,000

# ITEMS TO IMPROVE MANAGEABILITY

ESTIMATED COST OF REQUIRED IMPROVEMENTS:

\$ 532,000



PROJECT: 75 COLERIDGE	CAL 1-30 B DATE: 3/8/85
YEAR CONSTRUCTED: 1971 OCCUPANCY: Families NUMBER OF UNITS: 2 NUMBER OF BUILDINGS: 1 BUILDING TYPES: 3 Story BLDG CONSTRUCTION: Wood Frame SITE DESCRIPTION: Steep Front to Back	YEAR COMPREHENSIVELY MODERNIZED: N/A TYPE OF ROOF: Shingles HEATING SYSTEM: Forced Air HOT WATER SYSTEM: Water Heaters UTILITY ARRNGEMENT: Indiv Metered NUMBER OF ELEVATORS: 0 COMMUNITY BUILDING/SPACE: No
IMPRO	VEMENTS REQUIRED
HEALTH AND SAFETY ITEMS	
DETERIORATION REPAIRS	
\"	
ITEMS TO IMPROVE LIVEABILITY	
ITEMS TO IMPROVE MANAGEABILITY	
ESTIMATED COST OF REQUIRED IMP	PROVEMENTS:  INFO NOT AVAILABLE



Ţ	
PROJECT: 101 LUNDY LANE	CAL 1-30 C DATE: 3/8/85
YEAR CONSTRUCTED: 1971 OCCUPANCY: Families NUMBER OF UNITS: 2 NUMBER OF BUILDINGS: 1 BUILDING TYPES: 3 Story BLDG CONSTRUCTION: Wood Frame SITE DESCRIPTION: Corner Lot	YEAR COMPREHENSIVELY MODERNIZED: N/A TYPE OF ROOF: Shingles HEATING SYSTEM: Forced Air HOT WATER SYSTEM: Water Heater UTILITY ARRNGEMENT: Individ Metered NUMBER OF ELEVATORS: 0 COMMUNITY BUILDING/SPACE: No
IMPRO	VEMENTS REQUIRED
HEALTH AND SAFETY ITEMS	
DETERIORATION REPAIRS	
t <sub>f</sub> s.	
ITEMS TO IMPROVE LIVEABILITY	
ITEMS TO IMPROVE MANAGEABILITY	
TIERO TO THEROVE PANAGEAUTHITT	

INFO. NOT AVAILABLE

ESTIMATED COST OF REQUIRED IMPROVEMENTS:



1	
PROJECT: 25 SANCHEZ STREET	CAL 1-31 DATE: 3/8/85
YEAR CONSTRUCTED: 1972 OCCUPANCY: Elderly NUMBER OF UNITS: 90 NUMBER OF BUILDINGS: 1 BUILDING TYPES: 4 Story BUILDING CONSTRUCTION: Wood Fra	YEAR COMPREHENSIVELY MODERNIZED: N/A TYPE OF ROOF: Built-Up HEATING SYSTEM: Hot Water Boiler HOT WATER SYSTEM: Central Boiler UTILITY ARRANGEMENT: Master Metered TAME NUMBER OF ELEVATORS: 2 COMMUNITY BUILDING/SPACE: Yes
IMPRO	OVEMENTS REQUIRED
HEALTH AND SAFETY ITEMS Apartment Smoke Detectors Emergency Exit Lighting Pest Extermination	\$ 18,000 5,000 \$ 9,000 32,000x20%=39,000
DETERIORATION REPAIRS Paint Public Areas Roof Leaks Hall Carpeting Worn Apartment Painting Intercom System Problems Boiler Rehab Thermostatic Control Valves	\$ 15,000 45,000 16,000 135,000 5,000 20,000 \$ 36,000 272,000x20%=327,000
ITEMS TO IMPROVE LIVEABILITY	
ITEMS TO IMPROVE MANAGEABILITY Ventilation for Laundry Room	\$ 5,000x20%=6,000
ESTIMATED COST OF REQUIRED IM	PROVEMENTS: \$ 372,000



PROJECT: 1760 BUSH STREET	CAL	12	2	DATE:	3/8/85
YEAR CONSTRUCTED: 1972				SIVELY MOI	
OCCUPANCY: Elderly NUMBER OF UNITS: 108				Built-Up  Hot Wate	r Poilor
NUMBER OF BUILDINGS: 1					&Central Bolr
BUILDING TYPES: 7 Story BUILDING CONSTRUCTION: Con. Block					ster Metered
SITE DESCRIPTION: Slight Slope				DING/SPACE	
IMPRO	VEMEN	ITS	REQUIRE	D	
				_	
HEALTH AND SAFETY ITEMS Smoke Detectors for Units		\$	22,000	0	
Emergency Exit Lighting Pest Extermination		\$	4,000		20%=45,000
rest Extermination		<del>9</del>	11,000	37,0002	1208-43,000
DETERIORATION REPAIRS				_	
Apartment Painting Major Boiler Work	}	\$	162,000	0	
Replace Building Heating Pipes	3				000 651 000
Thermostatic Control Valves	}	\$	380,000	542,000	)x20%=651,000
\"					
ITEMS TO IMPROVE LIVEABILITY					
(PROVIDED)					
ITEMS TO IMPROVE MANAGEABILITY					
			_		

\$ 696,000

ESTIMATED COST OF REQUIRED IMPROVEMENTS:



PROJECT:	275 THRIFT	CAL 1-33	DATE:	3/8/85
OCCUPANCY NUMBER OF NUMBER OF BUILDING ' BLDG CONS'		YEAR COMPREHE TYPE OF ROOF: HEATING SYSTE HOT WATER SYS UTILITY ARRNO NUMBER OF ELE COMMUNITY BUIL	Asphalt EM: Forced STEM: Hot W GEMENT: Ind EVATORS: 0	Roofing Air Ater Heater iv Metered
	IMPRO'	VEMENTS REQUIF	RED	
	D SAFETY ITEMS rmination (Termites)	\$5,00	00x20% = 6,	000
DETERIORA Interior Exterior		\$ 1,50 		0%=4,000
ITEMS TO	IMPROVE LIVEABILITY			
Upgrade L	andscaping	\$1,000>	20% =2,000	
ITEMS TO	IMPROVE MANAGEABILITY			
ESTIMATE	ED COST OF REQUIRED IMP	ROVEMENTS:	\$ 12	,000



T						
PROJECT: 4101 NORIEGA	(	CAL 1-3	4	DATE:	3/8/85	
YEAR CONSTRUCTED: 1971 OCCUPANCY: Families NUMBER OF UNITS: 8 NUMBER OF BUILDINGS: 1 BUILDING TYPES: 3 Story Walk-UBUILDING CONSTRUCTION: Wood Free Site Description: Corner Lot	ip l	TYPE OF HEATING HOT WATH UTILITY E NUMBER	ROOF: SYSTEM ER SYSTEM ARRANGE R OF E	Shingles M: Indiv. TEM: Centi GEMENT: Ma	Forced Air ral Water H aster Meter 0	eater
IMPE	ROV	EMENTS :	REQUIR	ED		
HEALTH AND SAFETY ITEMS  Pest Extermination  Apartment Smoke Detectors  Additional Exterior Lighting		1,000 2,000 1,000	4,000	x20%=5,000	<u>)</u>	
DETERIORATION REPAIRS  Kitchen and Bathroom Plumbing Paint Public Stairs Repair Public Restroom Leaks Garage Doors Replace Signs Repair Forced Air Units	\$	8,000 3,000 1,000 4,000 1,000 8,000	25,00	0x20%=30,0	000_	
ITEMS TO IMPROVE LIVEABILITY Provide Play Areas Upgrade Landscaping	\$ \$	5,000	15,00	0x20%=18,0	000	
ITEMS TO IMPROVE MANAGEABILITY Provide Irrigation System	<u>Y</u> \$	2,000x	208=3,	000		
ESTIMATED COST OF REQUIRED IN	MPR	OVEMENT	S:	\$ 56	5,000	

56,000



4	PROJECT: 363 NOE STREET . CAL 1-34 DATE: 3/8/85	
	YEAR COMPREHENSIVELY MODERNIZED: N/A OCCUPANCY: Elderly TYPE OF ROOF: Built-Up and Shingles NUMBER OF UNITS: 22 HEATING SYSTEM: Hot Water Boiler NUMBER OF BUILDINGS: 1 HOT WATER SYSTEM: Solar & Cntrl Boile BUILDING TYPES: 3 Story UTILITY ARRANGEMENT: Master Metered BUILDING CONSTRUCTION: Wood Frame NUMBER OF ELEVATORS: 1 SITE DESCRIPTION: Slope Front to Back COMMUNITY BUILDING/SPACE: Yes	-
	IMPROVEMENTS REQUIRED	
	HEALTH AND SAFETY ITEMS Apartment Smoke Detectors \$ 5,000 Emergency Exit Lighting 3,000 Pest Extermination \$ 11,000 19,000x20%=23,000	
•	DETERIORATION REPAIRS  Boiler Improvements \$ 1,000 Halls Need Painting 17,000 Roof Leaks Through Boiler Room Floor 5,000 Apartment Need Painting 33,000 Outside Planter Boxes Need Replacement 2,000 Thermostatic Control Valves \$ 9,000 67,000x20%=81,000	
	<pre>ITEMS TO IMPROVE LIVEABILITY Better Ventilation in Bathrooms \$11,000x20% =14,000</pre>	
	ITEMS TO IMPROVE MANAGEABILITY	
	ESTIMATED COST OF REQUIRED IMPROVEMENTS: \$ 118,000	



	1	T	
•	PROJECT: 200 RANDOLPH CAN	L 1-34 DATE: 5/14/85	
	OCCUPANCY: Families TYN  NUMBER OF UNITS: 16 HEA  NUMBER OF BUILDINGS: 3 HOO  BUILDING TYPES: 3 Story Walk-up UT:  BUILDING CONSTRUCTION: Wood Frame I	PE OF ROOF: Shingles ATING SYSTEM: Indv. Forced Air WATER SYSTEM: Central Water Hea ILITY ARRANGEMENT: Master Metered	
	IMPROVEM	ENTS REQUIRED	
	HEALTH AND SAFETY ITEMS  Pest Extermination  Apartment Smoke Detectors  Provide Exterior Stair Railings  Additional Exterior Lighting  DETERIORATION REPAIRS  Kitchen and Bathroom Plumbing	$ \begin{array}{cccccccccccccccccccccccccccccccccccc$	
	Sliding Glass Doors (Better Security Paint Doors-Repair Locks, Mail Slot Apartment Flooring Apartment Painting Upgrade Hot Water System Paint Public Stairs Repair Property Line Fence Address Soil Erosion (Steep Areas) Garage Door Repairs Repair Forced Air Units	10,000 24,000 24,000 10,000 5,000 2,000 1,000 6,000 16,000	
	ITEMS TO IMPROVE LIVEABILITY Upgrade Landscaping	$130,000 \times 20\% = \boxed{156,000}$ $15,000 \times 20\% = \boxed{18,000}$	
	ITEMS TO IMPROVE MANAGEABILITY Provide Irrigation System	13,000 x 20% = 16,000	
	ESTIMATED COST OF REQUIRED IMPROV	EMENTS: \$ 213,000	



PROJECT:	2698 CALIFORNIA ST.	CAL 1-	35	DATE:	3/8/85	
OCCUPANCY NUMBER OF NUMBER OF BUILDING	TRUCTED: 1971 : Elderly UNITS: 40 BUILDINGS: 1 TYPES: 5 Story CONSTRUCTION: Wood Fra RIPTION: Corner Lot	TYPE O HEATIN HOT WA UTILIT me NUMB	F ROOF: G SYSTI TER SYS Y ARRAN ER OF I	Built-UEM: Hot Was STEM: Sola NGEMENT: N	ater Boiler ar & Cntrl Master Mete : 1	Boiler
	IMPRO	VEMENTS	REQUIE	RED		
Apartment	D SAFETY ITEMS Smoke Detectors Exit Lighting	\$	8,000	11,000x2	20%=14,000	
Repair Lo Rehab Boi	TION REPAIRS bby Ceiling Hole-Paint ler tic Control Valves	Lobby		,000	,000x20%=82	,000
	IMPROVE LIVEABILITY Required In Garden		\$ 2,	,000x20%=3	3,000	
ITEMS TO	IMPROVE MANAGEABILITY					
ESTIMATE	ED COST OF REQUIRED IMP	PROVEMEN	TS:	\$ 99	9,000	



ı	PROJECT: GREAT HIGHWAY	CAL 1-35	5	DATE:	3/8/85	
	YEAR CONSTRUCTED: 1971 OCCUPANCY: Families NUMBER OF UNITS: 16 NUMBER OF BUILDINGS: 4 BUILDING TYPES:2 Stry Twn Hous BUILDING CONSTRUCTION: Wood F: SITE DESCRIPTION: Flat	YEAR COM TYPE OF HEATING HOT WATE SE UTILITY rame NUMBER	MPREHE ROOF: SYSTE ER SYS ARRAN R OF E	NSIVELY MOI Shingles M: Indv. Fo TEM: Indv. GEMENT: Ind	DERNIZED: _1 Drced Air Water Heate	ers
	IMP	ROVEMENTS F	REQUIR	ED		
	HEALTH AND SAFETY ITEMS Apartment Smoke Detectors Pest Extermination Additional Exterior Lighting	\$ 6,400 1,600 \$ 8,000	16,000	x20%=20,000	<u>)</u>	
	DETERIORATION REPAIRS Kitchen and Bathroom Plumbing Doors, Locks and Mail Slots Apartment Flooring Some Forced Air Units Some Water Heaters Replace Missing Signs Parking Area Roofs Repair Fencing Repair Windows Apartment Painting Repairs to Electrical System Repair Leaks	10,000 24,000 10,000 5,000 1,000 5,000 8,000 16,000 24,000 16,000	143,00	0x20%=172,0	000	
	ITEMS TO IMPROVE LIVEABILITY Upgrade Landscaping	\$8,000x209	%=10,0	00		

ITEMS TO IMPROVE MANAGEABILITY
Provide Irrigation System \$13,000x20%=16,000

ESTIMATED COST OF REQUIRED IMPROVEMENTS:

\$ 218,000



		T	
PROJECT: 227 BAY STREET	CAL 1-36	DATE:	3/8/85
YEAR CONSTRUCTED: 1971 OCCUPANCY: Elderly NUMBER OF UNITS: 50 NUMBER OF BUILDINGS: 1 BUILDING TYPES: 4 Story BUILDING CONSTRUCTION: Wood Fr		: Urathane EM: Gas Wal STEM: Centr GEMENT: Ele ELEVATORS:	Foam I Heaters al Boiler ct.Check Meter
IMPI	ROVEMENTS REQUI	RED	
HEALTH AND SAFETY ITEMS Smoke Detectors For Apartments Emergency Exit Lighting Pest Extermination	\$ 10,000 4,000 \$ 6,000		8=24,000
DETERIORATION REPAIRS Hall Carpeting	\$ 20,000	x20%=24,000	
ITEMS TO IMPROVE LIVEABILITY			
ITEMS TO IMPROVE MANAGEABILIT	<u>Y</u>		
ESTIMATED COST OF REQUIRED IN	MPROVEMENTS:		

\$

48,000



PROJECT: 491-31ST AVE. C	AL 1-37	DATE:	3/8/85
OCCUPANCY: Elderly T NUMBER OF UNITS: 75 H NUMBER OF BUILDINGS: 1 HO BUILDING TYPES: 5 Story U BUILDING CONSTRUCTION: Wood Frame	TILITY ARRANG	Built-Up 1: Hot Wat EM: Solar GEMENT: M LEVATORS:	& Shingles er Boiler &Central Boile aster Metered 2
IMPROVE	MENTS REQUIRE	ED	
HEALTH AND SAFETY ITEMS Apartment Smoke Detectors Emergency Exit Lighting Security Outdoor Lighting In Gard Balcony Door Security (Lower Floo Pest Extermination Lock for Garden Fence Gate DETERIORATION REPAIRS Garage to Garden Door Thermostatic Control Valves			0%=95,000 0%=38,000
ITEMS TO IMPROVE LIVEABILITY			
ITEMS TO IMPROVE MANAGEABILITY			
ESTIMATED COST OF REQUIRED IMPRO	OVEMENTS:		T

\$

133,000



PROJECT: 939 EDDY STREET	CAL 1-39 A	DATE:	3/8/85
YEAR CONSTRUCTED: Unknown OCCUPANCY: Elderly NUMBER OF UNITS: 36 NUMBER OF BUILDINGS: 1 BUILDING TYPES: 4 Story BLDG CONSTRUCTION: Wood Frame SITE DESCRIPTION: Slight Slope	YEAR COMPREHEN TYPE OF ROOF: HEATING SYSTEM HOT WATER SYST UTILITY ARRNGE NUMBER OF ELEV COMMUNITY BUIL	Built-Up Hot Wat EM: Solar MENT: Ind ATORS: 1	ter Boiler &Centrl Boiler lividual Meters
IMPRO	OVEMENTS REQUIRE	D	
HEALTH AND SAFETY ITEMS Smoke Detectors for Units Emergency Exit Lighting Pest Extermination	\$ 8,000 3,000 18,000		20%=35,000
DETERIORATION REPAIRS ROOF Leak-Damage on Top Floor Repaint Top Floor Hallway Thermostatic Control Valves	\$10,000 5,000 17,000		20%=39,000
ITEMS TO IMPROVE LIVEABILITY Need Handicapped Access to Gard	den \$5,000	x20%=6,00	0
ITEMS TO IMPROVE MANAGEABILITY			
ESTIMATED COST OF REQUIRED IM	provemen <b>ts:</b> T	\$ 80	,000



PROJECT: 951 EDDY STREET	CAL 1-39 B	DATE:	3/8/85
YEAR CONSTRUCTED: Unknown OCCUPANCY: Elderly NUMBER OF UNITS: 24 NUMBER OF BUILDINGS: 1 BUILDING TYPES: 5 Story BLDG CONSTRUCTION: Wood Frame SITE DESCRIPTION: Slight Slope	TYPE OF ROOF: HEATING SYSTE HOT WATER SYS UTILITY ARRNG NUMBER OF ELE	Built-Umark	dual Forced Ai r&Centrl Boile dividual Meter
IMPRO	VEMENTS REQUIR	ED	
HEALTH AND SAFETY ITEMS Apartment Smoke Detectors Emergency Exit Lighting	\$ 5,00 3,00		20%=10,000
DETERIORATION REPAIRS Wood Windows In Poor Condition Interior Painting-Water damage	48,00 10,00		20%=70,000

ITEMS TO IMPROVE LIVEABILITY

ITEMS TO IMPROVE MANAGEABILITY

ESTIMATED COST OF REQUIRED IMPROVEMENTS:

\$ 80,000



